

Clinical Policy: Cochlear Implant Replacements

Reference Number: CP.MP.14 Date of Last Revision: 07/23 Revision Log Coding Implications

See <u>Important Reminder</u> at the end of this policy for important regulatory and legal information.

Description

This policy outlines medical necessity criteria for the replacement of cochlear implants and/or cochlear implant components. The cochlear implant has four basic components: a microphone, worn externally behind the ear, which picks up sounds; an external speech processor, which converts sounds to electrical signals; a transmitter and receiver/stimulator, which forward the signals; and implanted electrodes, which stimulate the fibers of the auditory nerve.⁶

Policy/Criteria

- I. It is the policy of health plans affiliated with Centene Corporation[®] that *replacement* of a cochlear implant(s) and/or its external components (external speech processor, controller, etc.) is considered **medically necessary** when any one of the following is present:
 - A. The existing device(s) is no longer functional and cannot be repaired;
 - B. A change in the member/enrollee's condition makes the existing unit(s) inadequate for the hearing-related activities of daily living and improvement is expected with a replacement unit(s);
 - C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years.
- II. It is the policy of health plans affiliated with Centene Corporation that *replacement or upgrade* of an existing, properly functioning cochlear implant and/or its external components (external speech processor, controller, etc.) is considered **not medically necessary** when requested only for convenience or to simply upgrade to a newer technology.

Background

Sensorineural hearing loss, or nerve deafness, is a type of hearing loss that results from problems with the inner ear, related to the cochlea, eighth nerve, internal auditory canal, or brain. A common cause of hearing loss in adults is presbycusis, a progressive condition caused by the loss of function of hair cells in the inner ear. Severe to profound hearing loss in children is most often related to genetics, prenatal, perinatal, or postnatal causes. A cochlear implant, an electronic device surgically placed under the skin, bypasses the hair cells and directly transmits sounds through multiple electrodes, which stimulate the auditory nerve. Once the auditory nerve is activated, signals are sent to the brain. The brain learns to recognize these signals and the person experiences this as hearing.

Cochlear implants have been studied since the 1950s and were approved by the FDA in adults in the mid-1980s.^{2,5} National Institute of Health (NIH) scientists determined cochlear implants to be cost beneficial.

Recent studies have been conducted evaluating the use of bilateral cochlear implants compared to unilateral implants. Many of these studies have shown that children obtained significantly



higher hearing thresholds in the bilateral implants. Speech recognition scores in noisy conditions were also improved in bilateral users, while speech perception outcomes in quiet conditions were mixed demonstrating differences for only two out of seven outcome measures.^{1,8} Studies also have shown better scores on sentence and word recognition tests for bilateral users.¹

Very little data has been published comparing differences between bilateral cochlear implants and cochlear implant with a hearing aid on the opposite ear. One small study showed improved localization abilities and speech perception scores for two former users of cochlear implant/hearing aid within the first six months after the second implant was activated. However, performance showed a slight decline after six months of use. Further studies are needed in this area to determine efficacy for bilateral cochlear implants in adults.¹

While evidence is increasing regarding the use of bilateral implants, bilateral implantation is not without problems. Limited nerve survival that remains may be asymmetrical, resulting in an unnatural pattern of neural activity in stimulation with electrical pulses. This asynchronous stimulation across devises might result in individual neural impulses which are unlikely to result in useful cues related to interaural differences. Also, bilateral implantation doubles the risks associated with surgical intervention and is very costly.²

Coding Implications

This clinical policy references Current Procedural Terminology (CPT®). CPT® is a registered trademark of the American Medical Association. All CPT codes and descriptions are copyrighted 2022, American Medical Association. All rights reserved. CPT codes and CPT descriptions are from the current manuals and those included herein are not intended to be all-inclusive and are included for informational purposes only. Codes referenced in this clinical policy are for informational purposes only. Inclusion or exclusion of any codes does not guarantee coverage. Providers should reference the most up-to-date sources of professional coding guidance prior to the submission of claims for reimbursement of covered services.

CPT®* Codes	Description
69949	Unlisted procedure, inner ear

HCPCS	Description	
Codes		
L8615	Headset/headpiece for use with cochlear implant device, replacement	
L8616	Microphone for use with cochlear implant device, replacement	
L8617	Transmitting coil for use with cochlear implant device, replacement	
L8618	Transmitter cable for use with cochlear implant device, or auditory osseointegrated	
	device, replacement	
L8619	Cochlear implant, external speech processor and controller, integrated system,	
	replacement	
L8621	Zinc air battery for use with cochlear implant device and auditory osseointegrated	
	sound processors, replacement, each	
L8622	Alkaline battery for use with cochlear implant device, any size, replacement, each	



HCPCS	Description
Codes	
L8623	Lithium ion battery for use with cochlear implant or auditory osseointegrated device
	speech processor, other than ear level, replacement, each
L8624	Lithium ion battery for use with cochlear implant device speech-
	processor, ear level replacement, each
L8627	Cochlear implant, external speech processor, component, replacement
L8628	Cochlear implant, external controller component, replacement
L8629	Transmitting coil and cable, integrated, for use with cochlear implant device,
	replacement

Initial approval date Added criteria for replacement of implants and components O6/13 Clarified policy language to discuss replacement of implants or components only Background updated Converted into new template Converted in II that replacements are not medically necessary when requested only for convenience/ to upgrade to newer technology. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the surrent processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	Reviews, Revisions, and Approvals		Approval Date
Added criteria for replacement of implants and components Clarified policy language to discuss replacement of implants or components only Background updated Converted into new template Converted to new template. References reviewed. ICD 10 codes added. Clarified in II that replacements are not medically necessary when requested only for convenience/ to upgrade to newer technology. References reviewed and updated. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. References reviewed and updated. Codes review. References reviewed and updated. References reviewed and updated. Codes review. References reviewed and updated. References reviewed and updated. Codes review. References reviewed and updated. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	Initial approval date	Date	
Clarified policy language to discuss replacement of implants or components only Background updated Converted into new template Converted to new template. References reviewed. ICD 10 codes added. Clarified in II that replacements are not medically necessary when requested only for convenience/ to upgrade to newer technology. References reviewed and updated. References reviewed and updated. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. References reviewed and updated. Codes review. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	**		06/13
components only Background updated Converted into new template Converted to new template. References reviewed. ICD 10 codes added. Clarified in II that replacements are not medically necessary when requested only for convenience/ to upgrade to newer technology. References reviewed and updated. References reviewed and updated. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. References reviewed and updated. COdes review. O6/19 References reviewed and updated. Codes review. References reviewed and updated. Codes review. O6/19 References reviewed and updated. Codes review. O6/20 Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External			09/14
Converted into new template Converted to new template. References reviewed. ICD 10 codes added. Clarified in II that replacements are not medically necessary when requested only for convenience/ to upgrade to newer technology. References reviewed and updated. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. References reviewed and updated. Codes review. References reviewed and updated. Codes review. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External			
Converted to new template. References reviewed. ICD 10 codes added. Clarified in II that replacements are not medically necessary when requested only for convenience/ to upgrade to newer technology. References reviewed and updated. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. Removed CPT 69717and 69718 and replaced with CPT 69949 References reviewed and updated. Codes review. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External			09/15
Clarified in II that replacements are not medically necessary when requested only for convenience/ to upgrade to newer technology. References reviewed and updated. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. Removed CPT 69717and 69718 and replaced with CPT 69949 References reviewed and updated. Codes review. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	Converted into new template		
requested only for convenience/ to upgrade to newer technology. References reviewed and updated. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. Removed CPT 69717and 69718 and replaced with CPT 69949 References reviewed and updated. Codes review. References reviewed and updated. O6/19 References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	Converted to new template. References reviewed. ICD 10 codes added.	09/16	09/16
References reviewed and updated. References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. Removed CPT 69717and 69718 and replaced with CPT 69949 References reviewed and updated. Codes review. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	Clarified in II that replacements are not medically necessary when	09/17	09/17
References reviewed and updated. Added criteria for sound processor replacement if it is over 5 years old. Removed CPT 69717and 69718 and replaced with CPT 69949 References reviewed and updated. Codes review. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External			
Added criteria for sound processor replacement if it is over 5 years old. Removed CPT 69717and 69718 and replaced with CPT 69949 References reviewed and updated. Codes review. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	References reviewed and updated.		
Removed CPT 69717and 69718 and replaced with CPT 69949 References reviewed and updated. Codes review. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	References reviewed and updated.		07/18
References reviewed and updated. Codes review. References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	Added criteria for sound processor replacement if it is over 5 years old.		10/18
References reviewed and updated. Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	Removed CPT 69717and 69718 and replaced with CPT 69949		
Annual review. References reviewed and updated. Coding reviewed, added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	References reviewed and updated. Codes review.		07/19
added codes L8621 and L8622. Replaced all instance of "member" with "member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	References reviewed and updated.		07/20
"member/enrollee." Changed "review date" in the header to "date of last revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	Annual review. References reviewed and updated. Coding reviewed,		07/21
revision" and "date" in the revision log header to "revision date." Sent for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External			
for specialist review. Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External			
Annual review completed. Removed "or" in I.A. and I.B. Background updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External			
updated with no impact to criteria. References reviewed and updated. Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External			
Annual review completed. Changed verbiage in I.C. from "A sound processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External		07/22	07/22
processor replacement if the current processor is at least five years old" to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External		0.7/2.4	0 = /
to "C. The existing component has reached the limit of its reasonable useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External		07/23	07/23
useful life. The reasonable useful life of a sound processor is not less than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	1		
than five years". Minor rewording with no clinical significance. Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External			
Background updated with no impact to criteria. ICD-10-CM Diagnosis Code table removed. References reviewed and updated. External	*		
Code table removed. References reviewed and updated. External			
·			
	specialist reviewed.		



References

- 1. American Academy of Audiology. American Academy of Audiology Clinical Practice Guidelines: Pediatric amplification. https://audiology-web.s3.amazonaws.com/migrated/PediatricAmplificationGuidelines.pdf 539975b3e7e9f1.74 471798.pdf Published June 2013. Accessed June 6, 2023.
- 2. United States Food and Drug Administration. Cochlear implants. http://www.fda.gov/MedicalDevices/ProductsandMedicalProcedures/ImplantsandProsthetics/CochlearImplants/default.htm. Published February 3, 2022. Accessed June 6, 2023.
- 3. Yosefof E, Hilly O, Ulanovski D, Raveh E, Attias J, Sokolov M. Cochlear implant failure: diagnosis and treatment of soft failures. *Acta Otorhinolaryngol Ital*. 2021;41(6):566 to 571. doi:10.14639/0392-100X-N1583
- 4. North HJD, Lloyd SKW. Hearing rehabilitation in neurofibromatosis type 2. *Adv Otorhinolaryngol*. 2018;81:93 to 104. doi:10.1159/000485526.
- 5. Year 2019 position statement: Principles and guidelines for early hearing detection and intervention programs. *J Early Hear Detect Interv.* 2019; 4(2):1 to 44.
- 6. Local coverage article: billing and coding: external components for cochlear implants (A53708). Centers for Medicare and Medicaid Services Web site. http://www.cms.hhs.gov/mcd/search.asp. Published October 1, 2015 (revised November 7, 2019). Accessed June 6, 2023.
- 7. Blevins NH. Presbycusis. UpToDate. www.uptodate.com. Updated April 18, 2022. Accessed June 3, 2022.
- 8. National Institute for Health and Care Excellence (NICE). Cochlear implants for children and adults with severe to profound deafness: Technology appraisal guidance [TA566]. Published March 7, 2019. https://www.nice.org.uk/guidance/ta566. Accessed June 6, 2023.

Important Reminder

This clinical policy has been developed by appropriately experienced and licensed health care professionals based on a review and consideration of currently available generally accepted standards of medical practice; peer-reviewed medical literature; government agency/program approval status; evidence-based guidelines and positions of leading national health professional organizations; views of physicians practicing in relevant clinical areas affected by this clinical policy; and other available clinical information. The Health Plan makes no representations and accepts no liability with respect to the content of any external information used or relied upon in developing this clinical policy. This clinical policy is consistent with standards of medical practice current at the time that this clinical policy was approved. "Health Plan" means a health plan that has adopted this clinical policy and that is operated or administered, in whole or in part, by Centene Management Company, LLC, or any of such health plan's affiliates, as applicable.

The purpose of this clinical policy is to provide a guide to medical necessity, which is a component of the guidelines used to assist in making coverage decisions and administering benefits. It does not constitute a contract or guarantee regarding payment or results. Coverage decisions and the administration of benefits are subject to all terms, conditions, exclusions and limitations of the coverage documents (e.g., evidence of coverage, certificate of coverage, policy, contract of insurance, etc.), as well as to state and federal requirements and applicable Health Plan-level administrative policies and procedures.



This clinical policy is effective as of the date determined by the Health Plan. The date of posting may not be the effective date of this clinical policy. This clinical policy may be subject to applicable legal and regulatory requirements relating to provider notification. If there is a discrepancy between the effective date of this clinical policy and any applicable legal or regulatory requirement, the requirements of law and regulation shall govern. The Health Plan retains the right to change, amend or withdraw this clinical policy, and additional clinical policies may be developed and adopted as needed, at any time.

This clinical policy does not constitute medical advice, medical treatment or medical care. It is not intended to dictate to providers how to practice medicine. Providers are expected to exercise professional medical judgment in providing the most appropriate care, and are solely responsible for the medical advice and treatment of members/enrollees. This clinical policy is not intended to recommend treatment for members/enrollees. Members/enrollees should consult with their treating physician in connection with diagnosis and treatment decisions.

Providers referred to in this clinical policy are independent contractors who exercise independent judgment and over whom the Health Plan has no control or right of control. Providers are not agents or employees of the Health Plan.

This clinical policy is the property of the Health Plan. Unauthorized copying, use, and distribution of this clinical policy or any information contained herein are strictly prohibited. Providers, members/enrollees and their representatives are bound to the terms and conditions expressed herein through the terms of their contracts. Where no such contract exists, providers, members/enrollees and their representatives agree to be bound by such terms and conditions by providing services to members/enrollees and/or submitting claims for payment for such services.

Note: For Medicaid members/enrollees, when state Medicaid coverage provisions conflict with the coverage provisions in this clinical policy, state Medicaid coverage provisions take precedence. Please refer to the state Medicaid manual for any coverage provisions pertaining to this clinical policy.

Note: For Medicare members/enrollees, to ensure consistency with the Medicare National Coverage Determinations (NCD) and Local Coverage Determinations (LCD), all applicable NCDs, LCDs, and Medicare Coverage Articles should be reviewed <u>prior to</u> applying the criteria set forth in this clinical policy. Refer to the CMS website at http://www.cms.gov for additional information.

©2016 Centene Corporation. All rights reserved. All materials are exclusively owned by Centene Corporation and are protected by United States copyright law and international copyright law. No part of this publication may be reproduced, copied, modified, distributed, displayed, stored in a retrieval system, transmitted in any form or by any means, or otherwise published without the prior written permission of Centene Corporation. You may not alter or remove any trademark, copyright or other notice contained herein. Centene[®] and Centene Corporation.

Corporation® are registered trademarks exclusively owned by Centene Corporation.